

From: [Rhotenberry, William](#)
To: [McAteer, Mike](#)
Cc: david.wade@oem.hctx.net; [Bernier, Roberto](#)
Subject: Re: 30 Aug 2017 -- ASPECT update 4 -- 1015
Date: Wednesday, August 30, 2017 11:59:48 AM
Attachments: [image001.png](#)

Ok I'll flip it when I get. Don't know how much it will tell us.

Sent from my iPhone

On Aug 30, 2017, at 11:57 AM, McAteer, Mike <mcateer.mike@epa.gov> wrote:

I'm checking to see if TCEQ wants to wait until later today (after you get the thermal image) to have a call with you all to discuss status of ARKEMA....



From: Rhotenberry, William
Sent: Wednesday, August 30, 2017 10:28 AM
To: david.wade@oem.hctx.net
Cc: McAteer, Mike <mcateer.mike@epa.gov>; Bernier, Roberto <bernier.roberto@epa.gov>
Subject: Fwd: 30 Aug 2017 -- ASPECT update 4 -- 1015

Haven't had a chance to look at it yet. David let's have a call soon to discuss.

Sent from my iPhone

Begin forwarded message:

From: "Thomas, Mark J." <Thomas.Markj@epa.gov>
To: "Rhotenberry, William" <Rhotenberry.William@epa.gov>
Cc: "Kudarauskas, Paul" <Kudarauskas.Paul@epa.gov>
Subject: 30 Aug 2017 -- ASPECT update 4 -- 1015

Bill please find attached preliminary data from the site.

Attached are a kmz and a jpeg. We have the full GIS if interested.

We have a gps fault on the scanner that we are looking into. I am having them deliver the raw data so we can manually give you an thermal image. It will take about 1.5 hours. to complete.

No detections of any vapors leaving the site. I expect to have the aircraft ready (fixed gps) by 1230.

Please let me know if you have any questions.

Mark Thomas, PhD
ASPECT Program Manager
Field Operations Branch
CBRN Consequence Management Advisory Division
EPA Office of Emergency Management
11201 Renner Blvd
Lenexa, KS 66219

Office: 913-551-5018
Cell: 513-675-4753